SIEMENS

SIREMOBIL Iso-C

SP

System Manual

Installation Instructions

Unpacking the Main Unit

© Siemens AG 1998
The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

Register 3
Print No.: SPR2-230.031.02.05.02

English
Doc. Gen. Date: 10.99

Replaces: SPR2-230.031.02.04.02



Fig.1
Tools required.

Fig. 2
- Cut off the strapping and remove ramp from pallet.



Fig. 3
- Unscrew clamp (1) and remove.
- Push screws through downwards.



Fig. 4
- Unscrew the stop block.
- Push screws through downwards.
- Pull stop block out from the side.



Fig. 5
- Unscrew clamps (2) at left and right (2 nuts each).
- Push screws through downwards.



Fig. 6
- For the removement of the transport holder (1/Fig. 6), the front support screws (2/Fig. 6) of the handles at the C-arm must be **loosened** on both sides.
- Unscrew the transport holder (1/Fig. 6) and remove it.
- Fasten the support screws (2/Fig. 6) back again.

Fig. 7
- Unscrew support and remove.



Fig. 8
- Unscrew clamps (3) and stop block at the X-ray tube (2 nuts each) and remove.
- Push screws through downwards.
- Unscrew holder (4), tip over and remove.



Fig. 9
- Position the ramp at the pallet, and nail them together.

Fig. 10
- Release the foot break, and pull the unit off the pallet and down the ramp.

Changes to previous version

Page 3
New text and new Fig. 6, Fig. 6 and 7 in Fig. 7 and 8 changed.

Page 4
Fig. 10 and 11 in Fig. 9 and 10 changed.

TD SD 24 / Arnold
TD SP / M. Heinlein
SMS Iselin / Fear